

1. Download and unzip the "X-Viberupdate".
2. Connect the X-Viber to your PC via USB cable and start the the X-Viber (Note that you must use fully charged battery or AC adapter).
3. Go into the "main menu" on the X-Viber and select "Info".
4. Open the "X-Viber Update" in your pc and right-click on "xloader.exe" and select "Run as administrator".
5. A new window will open, and in the middle of it must read: "Press 'Load' button to continue ..." otherwise you have to click on the "Try again" until "Press 'Load' button to continue ..." appears.
6. Click the "Browse" and select "XVIBER\_547.bin".
7. Click the "Load" and wait until it is completed.
8. Click "Exit" and turn off the X-Viber.
9. Disconnect the USB cable from Xviber and restart the X-Viber.